







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi




Pos.	Part No.
1	A 861 556 AA
2	A 861 557 NU
3	A 861 558 NU
4	A 861 559 NU
5	A 861 374 NU
6	A 861 560 NU
7	A 962 857 NU
8	A 861 367 NU
9	A 960 071 NU
10	A 962 595 NU
11	F 961 128 NU
12	A 861 561 NU
13	A 861 377 AA

1100mm





	A 861 330 AA	1000mm
14	B 961 024 AA	
15	B 0384 MY	
16	A 861 562 AA	
17	B 1759 AA	
18	BE 175 AA	



Ideal Standard


CERATHERM S200
A 7331 ..

0322 / A 868 990
Made in Germany



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com



1

10

1

2

3

1

12

6

4

5

1

2

3

4

8

9

10

5

6

7

8

5

6

7

8

5

6

7

8

9

10

11

12

9

10

11

12

9

10

11

12

9

10

11

12

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

Q=0%

Q=50%

Q=100%

P	bar	MAX. 10 0,5	5 1	Q (3 bar)
T	°C	MAX. 80	65 55	8 12